



DEPOTS.
423 BROOME ST. NEW YORK.
210 LAKE ST. CHICAGO.

M.L.SPERRY.
Secretary.

Waterbury, Conn. Nov. 14th 1891

O.C. Bobbsyphell
Asstt. U.S. Mint, Phila. Pa.,

My dear Sir

Yours of the 13th rec'd.

I do not think you will find any trace
of the wrong alloyed blanks. We have
given close attention to the matter and
we do not find any after our test. In
some unaccountable way a bar of metal
of wrong composition has been furnished the
gauge & width of the bronze penny metal.
The wrong blanks are so different in color
from the bronze blanks it would seem almost
almost impossible that they could pass your
inspectors when on counting boards if they
should get so far along as that. We will do all we can
now to prevent a recurrence of this trouble.

Yours very truly
C.P. Goss

675

RG104 E-1 Box 166

Waterbury, Conn.

Nov. 14. 1890

Scovill Mfg Co.

Explaining cause of
defective blanks.



[Abstract:] Explaining cause of defective blanks

The Scovill Mfg. Company
Waterbury, Conn.,

November 14, 1890

O.C. Bosbyshell
Supt. U.S. Mint, Philadelphia, Pa.

My dear Sir

Yours of the 13 received. I do not think you will find any more of the wrongly alloyed blanks, we have given close attention to the matter and we do not find any of these here. I've since encountered today a bar of metal of wrong mixture has been finished the gauge width of the bronze penny metal. The wrong blanks are so different in color from the bronze blanks it would seem impossible that they could pass your inspectors when on counting boards if they should get so far along as that. We will do all in our power to prevent a reoccurrence of this trouble.

Yours truly
C.P. Goss
Treasurer